


wh 4/21




THIS IS THE ONLY FURNACE WE HAVE IN OUR THREE BAY GARAGE

THE TWO FURNACES UP IN THE CEILING NEVER WORKED

DUE TO THE SIMPLE FACT OIL WILL NOT RUN UP HILL





WE NEED A REPLACEMENT FOUR BAY GARAGE